

## Pond Inlet is experiencing unfortunate events with the permafrost melting.



ne hamlet may have to do a mass disinterment of old graves as some of the coffins are exposed, slanted, or slight dent on the grave








There was also a mudslide in 2010 – just a kilometre away from the cemetery.












ond Inlet is experiencing unfortunate events with the permafrost melting.



he hamlet may have to do a mass disinterment of old graves as some of the coffins are exposed, slanted, or slight dent on the grave.



There were also 2 sinkholes in the community eroded from treams or snow runoff. They were filled with rocks and sand to fix.





## And more sinkholes 12 kilometres away from the community





